an a		MATION	CIA-RDP80-008 CE AGENCY REPORT	25X1 10A004200270004-2 REPORT NO. CD NO.
COUNTRY	East Germany			/ DATE DISTR. 28 May 1954
SUBJECT	Repair of Submarine	•	71.	NO. OF PAGES 1
PL/CE ACQUIRED	<u> </u>	25X1	635434	NO. OF ENCLS.
DATE OF INFO				SUPPLEMENT TO REPORT NO.
		ian i ang mang at pang at panggan ang bara da sa	ranga pagamanahanan 🧢 gerir da pribindah di di di dinangan sa	
AP THE HIMTON STATE	AIRS INFORMATION AFFECTING THE HATIONAL D S. WITHIN THE HEARING OF TITLE 16, SECTIL S. CODE, AS ABENDED. 175 TRAINSHISSION OF HITE TO OR RECEIVE BY AN UNAUTHORIZED. W THE REPRODUCTION OF THIS FORE IS PRO-	EFENSE CO	THIS IS UNE	VALUATED INFORMATION

25X1

On 12 March 1954, when source was at the Volkswertt Stralaund (the Stralaund nationalized shippard), he found out that the submarine concerned was to be entirely reconditioned. She was to get four torpede tubes. Her electrical equipment and the storage battery were entirely unserviceable. The new gear required for her reconditioning was being manufactured at the VES Elektro-Apparate Werke (Electrical Apparatus Works) in Berlin-Taeptow. The old periscopes also were entirely unusable, and new ones were to be manufactured by the Carl Zeiss firm in Jena. Her engines were to be replaced by engines from stocks left by the former German Navy and, of course, needed thorough overhaul prior to being installed.

25X1

Comment. The funds needed for the reconditioning of the submarine will approximate the cost of a new submarine.

 CLASSIFICATION SECRET
 25X1

 STATE
 NAVY
 #2 NSRB
 DISTRIBUTION

 ARMY
 2 AR
 2 FBI
 ...